

## **CALIFORNIA DEPARTMENT** OF TRANSPORTATION

TL-0113: LABORATORY ACCREDITATION REPORT

**Expiration Date: 11-19-2025** 

Laboratory: Aragon Geotechnical, Incorporated

Address: 16801 Van Buren Boulevard Riverside CA, 92504

**RSP #: 29** 

Lab QC Mgr.: Carlos Fernando Aragon

E-mail: fernando@aragongeo.com

**Telephone:** 951-776-0345 Inspected By: Benjamin Martinez

IA No.: 153

Caltrans Independent Assurance Staff accredited this laboratory to perform materials testing on Caltrans and state/federal-funded local agency construction projects. At the time of the inspection and assessment, this laboratory had all necessary equipment and documentation to perform the test methods indicated below.

Testing personnel\* shall be Caltrans certified and possess a current Caltrans Certification Form TL-0111 and/or AASHTO Proficiency Form TL-0115 prior to performing any sampling or testing.

## \*Accredited test methods as of 2024-08-21:

(# - NO certified tester at time of issuance)

CT 105 (JTCP)		CT 106		CT 125 ADMIX		CT 125 AGG	CT 125 BIT	CT 125 GEN
CT 125 HMA	Г	CT 125 CEM	Г	CT 201	Г	CT 202	CT 205	CT 206
CT 207	Г	CT 208	#	CT 213	Г	CT 216	CT 217	CT 226
CT 231	Г	CT 308	Г	CT 309		CT 370	CT 375	CT 382
CT 304		CT 204		CT 384	#	AASHTO T11	AASHTO T27	AASHTO R47
AASHTO R76		AASHTO T84		AASHTO T85		AASHTO T96	AASHTO T166	AASHTO T176
AASHTO T209		AASHTO T210	#	AASHTO T255		AASHTO T269	AASHTO T275	AASHTO T283
AASHTO T304	Г	AASHTO T308	Г	AASHTO T312		AASHTO T324	AASHTO T329	AASHTO T335
ASTM D4791	#	CT 227	Г	CT 229		CT 504	CT 518	CT 523.1 Section B.1 & B.2
CT 539	Г	CT 540	Г	CT 533		CT 543	CT 556	CT 557
CT 209	#	CT 211		CT 212	#	CT 214	CT 234	CT 235
CT 367	#	CT 371		CT 529	#	CT 125 AGG	CT 125 HMA	CT 523.2 Section B.3
CT 301		CT 389		CT 366		CT 521.1	CT 521.2	AASHTO T59 7 #
CT 306	Γ		Γ					•

## \*Accredited test methods as of 2025-01-13:

(# - NO certified tester at time of issuance)

01 324		TT				
* Please verify laboratory accredita	ation and associated test	ing personnel by	visitina t	he SIAD	website:	
	,					

https://sia.dot.ca.gov/	
Caltrans IA staff initially inspected and assessed the laboratory on	for the following items:
Facility Safety Manual	Copies of current applicable test methods
Laboratory Quality Control Manual	Calibration and service documentation
Proper test equipment	Calibration decals affixed to test equipment
<del></del>	



## CALIFORNIA DEPARTMENT OF TRANSPORTATION

TL-0113: LABORATORY ACCREDITATION REPORT

Caltrans Accreditation was prov	rided on by:		
	153		
IA Staff name	IA number	Signature	

For questions regarding this laboratory accreditation, please contact IA Staff: https://dot.ca.gov/programs/engineering-services/ia-staff-regional-contacts