



CALIFORNIA DEPARTMENT OF TRANSPORTATION

TL-0113: LABORATORY ACCREDITATION REPORT

Expiration Date: 11-19-2026

Laboratory: Aragon Geotechnical, Incorporated

Address: 16801 Van Buren Boulevard Riverside CA, 92504

RSP #: 29

Lab QC Mgr.: Carlos Fernando Aragon

E-mail: fernando@aragongeo.com

Telephone: 951-776-0345

Inspected By: Benjamin Martinez

IA No.: 153

Caltrans Independent Assurance Staff accredited this laboratory to perform materials testing on Caltrans and state/federal-funded local agency construction projects. At the time of the inspection and assessment, this laboratory had all necessary equipment and documentation to perform the test methods indicated below.

Testing personnel* shall be Caltrans certified and possess a current Caltrans Certification Form TL-0111 and/or AASHTO Proficiency Form TL-0115 prior to performing any sampling or testing.

***Accredited test methods as of 2025-11-19:**

(# - NO certified tester at time of issuance)

CT 105 (JTCP)	CT 106	CT 125 ADMIX	CT 125 AGG	CT 125 BIT	CT 125 GEN	
CT 125 HMA	CT 125 CEM	CT 201	CT 202	CT 205	CT 206	
CT 207	CT 208	# CT 213	CT 216	CT 217	CT 226	
CT 231	CT 308	CT 309	CT 370	CT 375	CT 382	
CT 304	CT 204	CT 384	# AASHTO T11	AASHTO T27	AASHTO R47	
AASHTO R76	AASHTO T84	AASHTO T85	AASHTO T96	AASHTO T166	AASHTO T176	
AASHTO T209	AASHTO T210	# AASHTO T255	AASHTO T269	AASHTO T275	AASHTO T283	#
AASHTO T304	AASHTO T308	AASHTO T312	AASHTO T324	# AASHTO T329	AASHTO T335	
ASTM D4791	# CT 227	CT 229	CT 504	CT 518	CT 523.1 Section B.1 & B.2	
CT 539	CT 540	CT 533	CT 543	CT 556	CT 557	
CT 209	# CT 211	CT 212	# CT 214	CT 234	# CT 235	
CT 367	# CT 371	# CT 529	# CT 125 AGG	CT 125 HMA	CT 523.2 Section B.3	
CT 301	CT 389	# CT 366	CT 521.1	CT 521.2	AASHTO T59 7	
CT 524	# CT 306					

***Accredited test methods as of 2026-04-15:**

(# - NO certified tester at time of issuance)

CT 314-H2	CT 372	ASTM D1557	ASTM D1633	ASTM D7196	
-----------	--------	------------	------------	------------	--

*** Please verify laboratory accreditation and associated testing personnel by visiting the SIAD website: <https://sia.dot.ca.gov/>**

Caltrans IA staff initially inspected and assessed the laboratory on _____ for the following items:

- | | |
|---|--|
| _____ Facility Safety Manual | _____ Copies of current applicable test methods |
| _____ Laboratory Quality Control Manual | _____ Calibration and service documentation |
| _____ Proper test equipment | _____ Calibration decals affixed to test equipment |

Please verify lab accreditation by visiting SIAD website: <https://sia.dot.ca.gov/>



CALIFORNIA DEPARTMENT OF TRANSPORTATION

TL-0113: LABORATORY ACCREDITATION REPORT

Caltrans Accreditation was provided on by:

IA Staff name

153
IA number

Signature

For questions regarding this laboratory accreditation, please contact IA Staff:
<https://dot.ca.gov/programs/engineering-services/ia-staff-regional-contacts>

Unofficial Copy