



CALIFORNIA DEPARTMENT OF TRANSPORTATION

TL-0113: LABORATORY ACCREDITATION REPORT

Expiration Date: 04-15-2027

Laboratory: Ninyo & Moore

Address: 7888 Cherry Avenue, Unit I Fontana CA, 92336

RSP #: 237

Lab QC Mgr.: James Dalgity

E-mail: jdalgity@ninyoandmoore.com

Telephone: 951-743-6157

Inspected By: Antonio Torres

IA No.: 168

Caltrans Independent Assurance Staff accredited this laboratory to perform materials testing on Caltrans and state/federal-funded local agency construction projects. At the time of the inspection and assessment, this laboratory had all necessary equipment and documentation to perform the test methods indicated below.

Testing personnel* shall be Caltrans certified and possess a current Caltrans Certification Form TL-0111 and/or AASHTO Proficiency Form TL-0115 prior to performing any sampling or testing.

***Accredited test methods as of 2026-04-15:**

(# - NO certified tester at time of issuance)

CT 105 (JTCP)	CT 106	#	CT 125 ADMIX	CT 125 BIT	CT 125 GEN	CT 125 CEM	
CT 201	CT 202		CT 205	CT 206	CT 207	#	CT 216
CT 217	CT 226		CT 227	CT 229	CT 231		CT 234
CT 235	#	CT 504	CT 518	CT 523.1 Section B.1 & B.2	CT 533		CT 539
CT 540		CT 556	CT 557	CT 523.2 Section B.3	CT 125 AGG	#	CT 125 HMA
CT 524	#	CT 521.1	CT 521.2				

*** Please verify laboratory accreditation and associated testing personnel by visiting the SIAD website:**

<https://sia.dot.ca.gov/>

Caltrans IA staff initially inspected and assessed the laboratory on _____ for the following items:

_____ Facility Safety Manual

_____ Laboratory Quality Control Manual

_____ Proper test equipment

_____ Copies of current applicable test methods

_____ Calibration and service documentation

_____ Calibration decals affixed to test equipment

Caltrans Accreditation was provided on by:

IA Staff name

168

IA number

Signature

For questions regarding this laboratory accreditation, please contact IA Staff:

<https://dot.ca.gov/programs/engineering-services/ia-staff-regional-contacts>