

# CALIFORNIA DEPARTMENT OF TRANSPORTATION

TL-0113: LABORATORY ACCREDITATION REPORT

**Expiration Date:** 06-18-2027

**Laboratory:** DeSilva Gates/Marysville

**Address:** 4713 Hammonton Road Marysville CA,  
95901

**RSP #:** 47

**Lab QC Mgr.:** Brandon Wheeler

**E-mail:** bwheeler@desilvagates.com

**Telephone:** 925-719-5417

**Inspected By:** Darrell Valasek

**IA No.:** 151

Caltrans Independent Assurance Staff accredited this laboratory to perform materials testing on Caltrans and state/federal-funded local agency construction projects. At the time of the inspection and assessment, this laboratory had all necessary equipment and documentation to perform the test methods indicated below.

Testing personnel\* shall be Caltrans certified and possess a current Caltrans Certification Form TL-0111 and/or AASHTO Proficiency Form TL-0115 prior to performing any sampling or testing.

**\*Accredited test methods as of 2026-06-18:**

(# - NO certified tester at time of issuance)

|               |   |             |  |             |  |             |  |             |  |             |  |   |
|---------------|---|-------------|--|-------------|--|-------------|--|-------------|--|-------------|--|---|
| CT 105 (JTCP) |   | CT 125 GEN  |  | CT 106      |  | CT 125 AGG  |  | CT 125 HMA  |  | CT 125 CEM  |  | # |
| CT 125 ADMIX  | # | CT 125 BIT  |  | CT 201      |  | CT 202      |  | CT 205      |  | CT 206      |  |   |
| CT 207        |   | CT 217      |  | CT 226      |  | CT 227      |  | CT 229      |  | CT 304      |  |   |
| CT 308        |   | CT 309      |  | CT 366      |  | CT 367      |  | CT 370      |  | CT 382      |  |   |
| AASHTO T11    |   | AASHTO T27  |  | AASHTO T84  |  | AASHTO T85  |  | AASHTO T166 |  | AASHTO T176 |  |   |
| AASHTO T209   |   | AASHTO T210 |  | AASHTO T269 |  | AASHTO T275 |  | AASHTO T283 |  | AASHTO T304 |  |   |
| AASHTO T308   |   | AASHTO T312 |  | AASHTO T329 |  | AASHTO T335 |  | ASTM D4791  |  | CT 234      |  |   |
| CT 235        |   | CT 371      |  | CT 306      |  | AASHTO R47  |  | AASHTO R76  |  | AASHTO T255 |  |   |
| AASHTO R90    | # |             |  |             |  |             |  |             |  |             |  |   |

**\* Please verify laboratory accreditation and associated testing personnel by visiting the SIAD website:**

**<https://sia.dot.ca.gov/>**

Caltrans IA staff initially inspected and assessed the laboratory on \_\_\_\_\_ for the following items:

\_\_\_\_ Facility Safety Manual  
\_\_\_\_ Laboratory Quality Control Manual  
\_\_\_\_ Proper test equipment

\_\_\_\_ Copies of current applicable test methods  
\_\_\_\_ Calibration and service documentation  
\_\_\_\_ Calibration decals affixed to test equipment

Caltrans Accreditation was provided on by:

\_\_\_\_\_  
IA Staff name

151  
\_\_\_\_\_  
IA number

\_\_\_\_\_  
Signature

For questions regarding this laboratory accreditation, please contact IA Staff:  
<https://dot.ca.gov/programs/engineering-services/ia-staff-regional-contacts>

Please verify lab accreditation by visiting SIAD website: <https://sia.dot.ca.gov/>