

CALIFORNIA DEPARTMENT OF TRANSPORTATION

TL-0113: LABORATORY ACCREDITATION REPORT

Expiration Date: 10-31-2026 Laboratory: Geocon

Address: 3160 Gold Valley Drive, Suite 800 Rancho Cordova CA, 95742

RSP #: 197

Lab QC Mgr.: Mark Repking

E-mail: repking@geoconinc.com

Telephone: 916-852-9118 Inspected By: Ram Sah **IA No.:** 132

Caltrans Independent Assurance Staff accredited this laboratory to perform materials testing on Caltrans and state/federal-funded local agency construction projects. At the time of the inspection and assessment, this laboratory had all necessary equipment and documentation to perform the test methods indicated below.

Testing personnel* shall be Caltrans certified and possess a current Caltrans Certification Form TL-0111 and/or AASHTO Proficiency Form TL-0115 prior to performing any sampling or testing.

*Accredited test methods as of 2025-10-31:

(# - NO certified tester at time of issuance)

CT 105 (JTCP)	CT 201	CT 202		CT 205		CT 216		CT 217	
CT 226	CT 229	CT 231		CT 308	П	CT 375		CT 504	
CT 518	CT 539	CT 540		CT 556	П	CT 557		CT 227	
AASHTO T166	AASHTO T209	AASHTO T269	П	AASHTO T275	П	AASHTO T308		CT 106	#
CT 309	CT 382	CT 234	#	CT 235	П	CT 301		AASHTO R47	
AASHTO R76	AASHTO T11	AASHTO T27		AASHTO T312	П	AASHTO T324	#	CT 125 GEN	
CT 125 HMA	CT 125 AGG	CT 211		CT 389	П				

* Please verify laboratory acci https://sia.dot.ca.gov/	reditation and associated testing pers	sonnel by visiting the SIAD website:				
Caltrans IA staff initially inspected	ed and assessed the laboratory on	for the following items:				
Facility Safety Man Laboratory Quality Proper test equipm Caltrans Accreditation was prov	ent	Copies of current applicable test methods Calibration and service documentation Calibration decals affixed to test equipment				
IA Staff name	132 IA number	Signature				

For questions regarding this laboratory accreditation, please contact IA Staff: https://dot.ca.gov/programs/engineering-services/ia-staff-regional-contacts