



CALIFORNIA DEPARTMENT OF TRANSPORTATION

TL-0113: LABORATORY ACCREDITATION REPORT

Expiration Date: 12-16-2026

Laboratory: Aragon Geotechnical, Incorporated - ML 2

Address: 16801 Van Buren Boulevard, Building B
(SEE NOTES) Riverside CA, 92504

RSP #: 106

Lab QC Mgr.: Carlos F. Aragon

E-mail: fernando@aragongeo.com

Telephone: 951-776-0345

Inspected By: Benjamin Martinez

IA No.: 153

Caltrans Independent Assurance Staff accredited this laboratory to perform materials testing on Caltrans and state/federal-funded local agency construction projects. At the time of the inspection and assessment, this laboratory had all necessary equipment and documentation to perform the test methods indicated below.

Testing personnel* shall be Caltrans certified and possess a current Caltrans Certification Form TL-0111 and/or AASHTO Proficiency Form TL-0115 prior to performing any sampling or testing.

***Accredited test methods as of 2025-12-16:**

(# - NO certified tester at time of issuance)

AASHTO T27	#	AASHTO T166	#	AASHTO T255	#	CT 216	#	CT 226	#	CT 375	#
CT 231		CT 125 AGG		CT 125 HMA		CT 201	#	CT 202	#	CT 304	#
AASHTO R76	#	AASHTO T11	#	AASHTO R47	#	AASHTO T329	#	CT 125 GEN			

*** Please verify laboratory accreditation and associated testing personnel by visiting the SIAD website:**

<https://sia.dot.ca.gov/>

Caltrans IA staff initially inspected and assessed the laboratory on _____ for the following items:

- | | |
|---|--|
| _____ Facility Safety Manual | _____ Copies of current applicable test methods |
| _____ Laboratory Quality Control Manual | _____ Calibration and service documentation |
| _____ Proper test equipment | _____ Calibration decals affixed to test equipment |

Caltrans Accreditation was provided on by:

_____	153	_____
IA Staff name	IA number	Signature

For questions regarding this laboratory accreditation, please contact IA Staff:
<https://dot.ca.gov/programs/engineering-services/ia-staff-regional-contacts>